## **INSPECTION REPORT**

INST ECTION KET OKT			
PERMIT NUMBER:	BP-15-00281	OWNER'S NAME:	MCDANIEL
DATE:	8/9/2016	TYPE:	Mechanical and plumbir
TIME STARTED:	10:53 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-14-12051-0506		
<ol> <li>DWV at 5#-ok</li> <li>H20 at 80#-ok</li> <li>Exhaust duct ok</li> <li>Fireplace will be electric</li> <li>Whole house ventilation system on air handler advised in lieu of vented windows</li> <li>Soffit framing ok. Post down under rafter ends, at trusses, to top plate per plan. Can be seen on interior of house</li> </ol>			
INSTRUCTIONS: Ok to cover soffits  NEXT INSPECTION: Framing			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
INCRECTION REQUIEST LINE, FOO OCC 7504			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506