INSPECTION REPORT

PERMIT NUMBER:	BP-15-00284	OWNER'S NAME:	COWGER
DATE:	5/19/2016	TYPE:	Mechanical
TIME STARTED:	2:02 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-29050-0244		
1. DWV has leak 2. Fireplace roug 3. Mechanical of	gh ins ok	ter leak is fixed	
NEXT INSPECTION: Framing/DWV			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iessica.contratto @co.kittitas.wa.us