INSPECTION REPORT

TYPE:

OWNER'S NAME: JONES

Exterior shear

PERMIT NUMBER: BP-15-00288

DATE:

7/14/2015

TIME STARTED	: 9:34 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER	: 17-18-07060-0014		
1. tighte	en up upper edge nailing betv	veen master bed window	/S
	that interior shear walls exte		
3. 3 HT	T5 hold downs missing on S	garage wall	
INSTRUCTIONS	tighten up panel, ok to cov	er. Will need to see hold	downs or approved substitute by
NEXT INSPECTI	ON: plumb/mech		
RE-INSPECTION		YES	\$
IF	F REQUIRED, RE-INSPECTION FEES	MUST BE PAID PRIOR TO SCH	IEDULING A RE-INSPECTION
	QUESTIONS? PLEASE CONTACT T	HE INSPECTOR AT THE FOLLO	WING E-MAIL ADDRESS:
		iessica.contratto @co.	kittitas.wa.us
• IN	SPECTION REQUEST LINE: www. 411 N. Ruby Street, Suite 2, Eller		
	• • •	.	