

KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00288	OWNER'S NAME:	JONES
DATE:	9/18/2015	TYPE:	Framing
TIME STARTED:	9:26 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-18-07060-0014		

1. T brace	es needed trusses CH4,5,6
2. nut mis	sing on hold down in bed #2 wall
3. 6x6 pos	st needed under girder truss per plan at master bed entry
4. 6x6 und	der girder truss bed #3 entrance/foyer area. 4x currently
5. full bea	ring under 4x12 porch beam in garage wall
6. fireplac	e chimney not installed. Must see before cover
7. fireplac	e top standoff not installed for combustible clearances
8. fireplac	e to be installed on solid platform if raised off floor per install manual page
9/Framin	9
9. energy	credit for water heater probably won't be met with b-vent type gas heater. May
want to	consider insulating floor to R-38 since windows qualify for efficient envelope
credit	

INSTRUCTIONS: complete above, call for re-inspection

NEXT INSPECTION: re-inspect

RE-INSPECTION FEE DUE?

YES

V NO

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

iessica.contratto @co.kittitas.wa.us

\$

• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506