## **INSPECTION REPORT**

PERMIT NUMBER:		BP-15-00292	OWNER'S NAME:	STRADER	
DATE:		9/28/2015	TYPE:	Exterior shear	
TIME STARTED:		11:49 AM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-15-19050-0145			
	Strap missing at storage room wall				
	2. Engineer fix for strap fix at garage man door interior shearwall				
	3. Straps on chimney chase to trusses				
	4. Tighten up P1-2 nailing on paint marked walls				
	5. engineer approval for omittance of floor to floor straps at front balloon framed wall				
INSTRUCTIONS: complete above, re-inspect					
NEXT INSPECTION: re-inspect					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>					