INSPECTION REPORT

PERMIT NUMBER:	BP-15-00393	OWNER'S NAME:	FORTUNE CREEK
DATE:	10/26/2015	TYPE:	Framing
TIME STARTED:	10:19 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-15-07061-0030		
1. Truss brace missing A01			
2. Draftstop top of duct chase to attic upstairs			
3. A35 clips in laundry area per roof framing page			
4. Downstairs bath hold down correction not addressed			
5. LSL in downstairs stair opening not nailed to hanger			
6. SDS screws at 8"o.c. in deck ledgers			
7. move heat register down below framing in downstairs closet			
8. A35 clips to top plate in downstairs per framing page			
9. Gas line in rec room. Fireplace being installed? Omitted on plan. Additional fees and			
inspection may be required if added			
INSTRUCTIONS: complete above, do not insulate.			
NEXT INSPECTION: re-inspection			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			