



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00687

OWNER'S NAME: CARLSON

DATE: 4/11/2017

TYPE: Mechanical and plumbir

TIME STARTED: 3:57 PM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 20-15-20058-0132

1. Mechanical Rough In OK. Supply/Return OK. Venting OK.
2. Plumbing Rough In OK. DWV on Stack Supply Live at 60#/15min.
3. NOTE: Verify Beam Pocket Detail In Drawing. Porch Beams Do Not Appear Adequat e.

INSTRUCTIONS: OK to Call For Framing When Ready.

NEXT INSPECTION: Framing

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ [jeremy.haberman @co.kittitas.wa.us](mailto:jeremy.haberman@co.kittitas.wa.us)

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506