



KITITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-16-00696

OWNER'S NAME: MACKEY

DATE: 2/2/2017

TYPE: Floor framing

TIME STARTED: 12:44 PM

INSPECTOR: Justin Bennett

MAP NUMBER: 20-15-29050-0140

1. Floor Framing Ok
2. NOTE: Strip footing missing @ south P1-6 pony wall - Verify @ next inspection

INSTRUCTIONS: Complete strip footing/Ok to cover

NEXT INSPECTION: Exterior Shear

RE-INSPECTION FEE DUE?  NO  YES \$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  
ADDRESS: justin.bennett @co.kittitas.wa.us

**INSPECTION REQUEST LINE: 509-962-7694**

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506