



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00696

OWNER'S NAME: MACKEY

DATE: 3/24/2017

TYPE: Shearwalls

TIME STARTED: 1:55 PM

INSPECTOR: Justin Bennett

MAP NUMBER: 20-15-29050-0140

1. Exterior Shear Ok
2. HD's Ok
3. Straps Ok
4. Interior Shear Ok
5. Strip footing missing @ P1-6 underfloor
6. Strip footing missing @ garage/trash room

INSTRUCTIONS: Ok to cover Exterior

NEXT INSPECTION: Plumb/Mech

RE-INSPECTION FEE DUE? NO YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ justin.bennett@co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506