INSPECTION REPORT

PERMIT NUMBER:	BP-16-00726	OWNER'S NAME:	HERBIG
DATE:	5/17/2017	TYPE:	Footings
TIME STARTED:	10:28 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	21-14-09056-0003		
 Provide ledger off garage per 11/S3.2 or engineer Ok - not bearing on fdn Provide Engineer fix @ North wall per 3/S3.0 FIr Framing not attached per 5/S3.0 - hangers not bearing on fdn Blocking not per 11/S3.1 @ Living Rm (A35's) (3) 2x4's missing @ foyer bearing wall (2) 2x6 missing @ foyer framing 5-1/8"x7.5 GLB not installed @ foyer flr framing 4x6 post south of Foyer flr framing not installed 5-1/8x7.5 GLB not installed south or Foyer flr framing (2) 2x6 not installed @ bearing wall south of Foyer Flr framing A35's not installed @ south Foyer wall per 6/S3.0 South exterior wall not installed per 4/S3.0 4x6 posts (2) locations not insalled for SW2 SW2 @ Family Rm not sheeted per shear schedule DO NOT COVER INSTRUCTIONS: DO NOT COVER/Complete above or provide engineers approval			
NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE DUE? V NO YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL

<u>iustin.bennett</u> @co.kittitas.wa.us

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506