



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-16-00732

OWNER'S NAME: FORTUNE CREEK

DATE: 5/30/2017

TYPE: Framing

TIME STARTED: 10:22 AM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 19-15-07061-0033

1. NOTE: Not Ready for Framing Inspection. Plumbing, Mechanical Not Complete.
2. NOTE: Shear Inspection Performed.
3. HDU's Must Connect to Two Full Height Studs Throughout. Block Header. Coil Strap to Top Plate.
4. Panel Edge Blocking In Shear Walls Throughout Not Installed. Verify Throughout. Specifically Upstairs.
5. Floor To Floor Straps Missed On NE Corner. Bubbled on Permit Set.

INSTRUCTIONS: DO NOT COVER EXTERIOR.

NEXT INSPECTION: Re Inspection.

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: jeremy.haberman @co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506