INSPECTION REPORT

| INSI ECHON KEI OKI | | | |
|--|------------------|---------------|-------------------------|
| PERMIT NUMBER: | BP-16-00765 | OWNER'S NAME: | BRESTER |
| DATE: | 4/14/2017 | TYPE: | Insulation and mechanic |
| TIME STARTED: | 11:32 AM | INSPECTOR: | Jessica Contratto |
| MAP NUMBER: | 20-13-11051-0915 | | |
| 1. Wall insulation R-21 batt 2. Vault insulation R-38 3. Provide class I vapor retarder(sheet polyethylene) at exterior walls or provide proof that paint or primer meets perm rating of 4. Complete exhaust fan ducting 5. Install range vent. Minimum 6" smooth duct 6. Install gas line to exterior of home and provide pressure test of 15# minimum 1. Line to tank does not need to be installed at this time 7. Current chosen energy credit for water heater cannot be used for electric. | | | |
| NEXT INSPECTION: Re-inspect | | | |
| RE-INSPECTION FEE | DUE? NO YES | | \$ |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL | | | |

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:_

iessica.contratto @co.kittitas.wa.us

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506