INSPECTION REPORT

TYPE:

OWNER'S NAME:

EIDE MOUNTAIN HOMES

Floor framing

PERMIT NUMBER:

DATE:

FO-14-00053

8/25/2014

TIME STARTED: MAP NUMBER:		2:21 PM	INSPECTOR:	Jessica Contratto
		20-15-20058-014	}	
1.	1. missing point load blocking in master bath doorways (missing on one side) 2 places			
2.	2. missing block at launry and pantry entries (1 each)			
3.	3. finish rim board			
INSTRUCTIONS: complete above, send pics to email or see at next inspection. Ok to cover				
NEXT INSF	PECTION:	shearwalls		
RE-INSPEC	CTION FEE	DUE? NO .	YES	\$
	IF REQ	UIRED, RE-INSPECTION FEES MUST	BE PAID PRIOR TO SCI	HEDULING A RE-INSPECTION
	QU	ESTIONS? PLEASE CONTACT THE IN	SPECTOR AT THE FOLLO	DWING E-MAIL ADDRESS:
		je	ssica.contratto @co	.kittitas.wa.us
		TION REQUEST LINE: <u>www.co.k</u> 1 N. Ruby Street, Suite 2, Ellensbur _i		