APPENDIX A Site Photographs

PHOTO 1: Upstream area from bridge, view to the west



PHOTO 4: Downstream area from top of bridge at the Site



PHOTO 2: Upstream right bank



PHOTO 5: Downstream right bank



PHOTO 3: Right bank Ecology block abutment view downstream



PHOTO 6: Downstream left bank



Site Photographs (Photographs 1 through 6)

Geotechnical Summary Memo Johnson Property Manastash Creek Channel Migration Zone Study 11810 Manastash Road, Ellensburg, Washington

Aspect	MAY-2024	ABM/ETB	FIGURE NO.
CONSULTING	рноцестма. 240155	REV BY	A-1

PHOTO 7: Creek left bank downstream of bridge, view to the northwest



PHOTO 10: Abandoned automobile armoring creek left bank



PHOTO 8: Creek bifurcation near eastern property line, view to the north



PHOTO 11: Engineered bank armoring 3 miles upstream of Site



PHOTO 9: Gravel bar and woody in creek near east property line, view to the west



PHOTO 12: Manastash Road bridge 3 miles upstream of Site



Site Photographs (Photographs 7 through 12)

Geotechnical Summary Memo Johnson Property Manastash Creek Channel Migration Zone Study 11810 Manastash Road, Ellensburg, Washington

Aspect	MAY-2024	ABM/ETB	FIGURE NO.
CONSULTING		REV BY	A-2

PHOTO 13: View towards subject property from Manastash Road




PHOTO 16: Talus slopes south of proposed new structure



PHOTO 14: View to the north-northwest from Property driveway



PHOTO 17: Proposed new structure location, view to the south



PHOTO 15: Basalt bedrock cliffs and talus slopes above north side Manastash Road, view to the east




PHOTO 18: Utility test pit near proposed new structure location



Site Photographs (Photographs 13 through 18)

Geotechnical Summary Memo Johnson Property Manastash Creek Channel Migration Zone Study 11810 Manastash Road, Ellensburg, Washington

Aspect	MAY-2024	ABM/ETB	FIGURE NO.
Aspect		REV BY	A-3