



Approximate location of previous slope mitigation work. Mitigation involved drains and grading to drain water from slope. Water drains into roadside swale on South side of Cul-de-Sac.

Approximate Extent of Landslide and Location of Cracking

PSE Electrical Vault

PSE Underground Power Service to Residence

Waterline from Community Well to Residence

Approximate Property Boundary

Top of Cut Slope for Building Pad Excavation

Photo 1, @ Vault looking North to House

Photo 2, East of Vault looking West Along Road and along road showing head scarp of slide

Photo 4, North of Vault showing top of slide and vault settlement

Photo 5, @ Toe of Slope looking up and east at cut slope failure

Photo 6, @ Toe of Slope looking east along toe

Photo 5, @ Toe of Slope near mid point of cut showing local cut failure and small slide zone causing heave of existing grade near house

Caseo Residence  
561 Palouse Dr. Cle Elum, WA  
Kittitas County Parcel # 953974

4/6/2021

Pg. 1/1

Slope Failure