KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

# INSPECTION REPORT

| | | | |
|---|---|---|---|
| **PERMIT NUMBER:** | BP-13-00198 | **OWNER'S NAME:** | PAUL NW INVESTMENTS |
| **DATE:** | 9/19/2014 | **TYPE:** | Multiple (see notes) |
| **TIME STARTED:** | 11:42 AM | **INSPECTOR:** | Amber Green |
| **MAP NUMBER:** | 20-15-19051-0071 | | |

| | |
|---|---|
| | 1. Drywall needs to be continuous from the top plate to the bottom side of the roof sheati |
| | ng in the attic area. |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

**INSTRUCTIONS:** Complete Above, Re-Call Inspection.

**NEXT INSPECTION:** Re-Inspection

**RE-INSPECTION FEE DUE?** ☑ **NO** ☐ **YES** **$ _____**

***IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION***

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____amber.green **@co.kittitas.wa.us**