KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00037	**OWNER'S NAME:**	GALLIHER
DATE:	8/5/2016	**TYPE:**	Insulation
TIME STARTED:	11:07 AM	**INSPECTOR:**	Mike Flory
MAP NUMBER:	19-16-14030-0010		

1. Add firestops at dropped ceilings around interior walls. Draft stop can be so lid block or filled tight with insulation. If using insulation it must go up tig ht to plate and down minimum of 18" below ceiling.
2. Spray foam or insulate behind duct North wall second floor.

INSTRUCTIONS: Complete firestop at dropped ceiling and stairs, then call for reinspection of insulation. OK to cover the rest of walls and ceiling with sheetrock. Do not cover areas od firestop prior to inspection.

NEXT INSPECTION: Re-Insulation

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$ _____**

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: mike.flory **@co.kittitas.wa.us**

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506