KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-14-00390	**OWNER'S NAME:**	BADDA
DATE:	8/8/2014	**TYPE:**	Footings
TIME STARTED:	3:25	**INSPECTOR:**	Mike Flory
MAP NUMBER:	20-16-14000-0002		

	1. TOO MUCH LOOSE SOILS IN AND UNDER BOX PADS
	2. BACK SIDE OVER EXCAVATED AND BOX PADS TOO CLOSE TO CRUMBLING BANK EDGE
	3. FORMS TO BE SET UP WITH BAR TIED
	4. COMPACTION TEST REQUIRED DUE TO OVEREXCAVATION AND PROXIMITY TO CUT
	5. DO NOT POUR

INSTRUCTIONS: DO NOT POUR - HAVE COMPACTION TESTING DONE AND SET FORMS UP WITH BAR TIED

NEXT INSPECTION: RE-INSPECT ISOLATED FOOTINGS

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$ _____**

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

mike.flory **@co.kittitas.wa.us**