KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00424	**OWNER'S NAME:**	BOETTCHER/DONIO
DATE:	3/10/2016	**TYPE:**	Rough-in plumbing
TIME STARTED:	11:17 AM	**INSPECTOR:**	Jeremy Haberman
MAP NUMBER:	20-14-13050-0027		

1. NOTE: CORRECTIONS OUTSTANDING FROM INITIAL SHEAR INSPECTION.
2. Doorway cut into interior shearwall in guest bed closet to make mechanical ro om access.
3. Hold downs missing in pantry and art room walls
4. HDQ8 in trash room missing
5. All hold downs must connect to 2 full height studs.
6. Add blocking in p-2 wall upstairs bedroom. lay flat and extend as far as far as possible in bay.
7. Rough In Plumbing OK. DWV at 5#/15min. Supply at 80#/15min. OK.

INSTRUCTIONS: Complete Shear Corrections and Mechanical Inspection Prior to Requesting Framing Inspection.

NEXT INSPECTION: Shear/Mechanical

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$ _____**

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:_____jeremy.haberman **@co.kittitas.wa.us**

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506