KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00848	**OWNER'S NAME:**	FORTUNE CREEK LLC
DATE:	3/21/2016	**TYPE:**	Exterior shear
TIME STARTED:	12:43 PM	**INSPECTOR:**	Jessica Contratto
MAP NUMBER:	19-15-07061-0034		

1. Garage lateral restraint panels need to be sheathed per portal frame. Sheathing must span over header and down wall. Stitch nail per plan 3"
2. North shearwalls that ars P1-2-10D are not nailed with 10D nails. Edge blocking needs to be 3x
3. Stitch nail multiple members where hold downs are attached if not done
4. Missing HDU8 in utility room

INSTRUCTIONS: complete above, re-inspect

NEXT INSPECTION: re-inspect

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$ _____**

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:_____jessica.contratto **@co.kittitas.wa.us**

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506