KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00858	**OWNER'S NAME:**	GARDNER
DATE:	7/14/2016	**TYPE:**	Floor framing
TIME STARTED:	2:02 PM	**INSPECTOR:**	Jessica Contratto
MAP NUMBER:	18-19-12000-0002		

1. Cannot locate plans
2. Rubberized membrane, such as Vycor, must be used between joist hangers and treated sill plate, since Zmax hardware is not used

INSTRUCTIONS: Correct above, have approved stamped plans on site. No further inspections will be performed without approved plans

NEXT INSPECTION: Re-inspect

RE-INSPECTION FEE DUE? ☑ **NO** ☐ **YES** **$** _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: jessica.contratto **@co.kittitas.wa.us**

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506