INSPECTION REPORT

TYPE: Insulation

PERMIT NUMBER: BP-14-00397 OWNER'S NAME: CAREY

9/29/2015

DATE:

TIME STARTED:	10:01 AM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	21-14-34061-0004		
Engineering Still Required for Blocking Correction in Basement.			
2. Enginee	ering Still Required for Retainir	ng Walls Surroundin	g the Structure.
3. Insulation	on OK.		
INSTRUCTIONS: [OO NOT COVER. Provide Eng	jineering Via Email t	o Inspector.
NEXT INSPECTION:	Reinspect		
RE-INSPECTION FEI	E DUE? NO	YES	\$
IF RE	QUIRED, RE-INSPECTION FEES MUS	T BE PAID PRIOR TO SCI	HEDULING A RE-INSPECTION
Q	UESTIONS? PLEASE CONTACT THE I	NSPECTOR AT THE FOLLO	DWING E-MAIL ADDRESS:
	ie	remv.haberman @co	.kittitas.wa.us
	CTION REQUEST LINE: www.co. 11 N. Ruby Street, Suite 2, Ellensbu		
	nawy ources, June 2, Enerithal		2 303 302 7300