INSPECTION REPORT

PERMIT NUMBER:	BP-14-00449	OWNER'S NAME:	SINNETT
DATE:	3/26/2015	TYPE:	Rough-in plumbing
TIME STARTED:	11:37 AM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	20-14-14050-0925		
1. Gas F	Piping at 9#. 15#/15min. I	Required.	
2. Disconnect Furnaces Prior to Reinspection.			
3. Mechanical Room Floor Register Not Connected.			
4. Firepl	aces Not Installed/Drafts	top Not Comple	ete.
5. Underground Gas Lines Not Run to Outdoor Fireplace/Outdoor BBQ. Will Require Isolated P			
ressure Test.			
6. Exhaust Venting OK.			
INSTRUCTIONS: Make Corrections Above.			
NEXT INSPECTION:	Re Inspect		
RE-INSPECTION FEE	DUE? NO YE	S	\$
IF REC	QUIRED, RE-INSPECTION FEES MUST B	E PAID PRIOR TO SCHE	DULING A RE-INSPECTION
Ql	JESTIONS? PLEASE CONTACT THE INSP	PECTOR AT THE FOLLOW	/ING E-MAIL ADDRESS:
	jeren	ny.haberman @co.k	ittitas.wa.us
	CTION REQUEST LINE: www.co.kit 11 N. Ruby Street, Suite 2, Ellensburg,		