INSPECTION REPORT

TYPE:

OWNER'S NAME: CHRYSANTHAKOPOU

Shearwalls

PERMIT NUMBER: BP-14-00784

DATE:

7/6/2015

| TIME STARTED: | 11:34 AM | INSPECTOR: | Justin Bennett |
|-------------------|---|-------------------------------|-------------------------|
| MAP NUMBER: | 20-17-31051-0001 | | |
| 1. Provide | galvanized nails at bottom p | olate @ rear of building | |
| | edge blocking per detail 1/S | | |
| 3. Tighten | up field nailing (@ 12" OC) | throughout | |
| 4. Provide | anchor bolts @ 48" OC per | detail 1/SD2 | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| INSTRUCTIONS: N | Make corrections above/Re-I | nspection | |
| | | | |
| NEXT INSPECTION: | Re-Inspection | | |
| RE-INSPECTION FEI | E DUE? V NO | YES | \$ |
| IF RE | QUIRED, RE-INSPECTION FEES MU | — JST BE PAID PRIOR TO SCH | EDULING A RE-INSPECTION |
| Q | UESTIONS? PLEASE CONTACT THE | INSPECTOR AT THE FOLLO | WING E-MAIL ADDRESS: |
| | · | iustin bennett @co. | kittitas.wa.us |
| | CTION REQUEST LINE: <u>www.c</u> 11 N. Ruby Street, Suite 2, Ellensk | | |
| | | | |