INSPECTION REPORT

PERMIT NUMBER:		BP-15-00143	OWNER'S NAME:	BV RESORT HOMES
DATE:		12/30/2015	TYPE:	Exterior shear
TIME STARTED:		10:52 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		20-15-19051-0038		
1	. Exterior na	ailina ok		
	Hold down in garge entry and master bedroom not connected to proper full height studs.			
	Engineer fix or retrofit approval needed			
	3. 2 hold downs missing at interior shearwall at stairs			
	4. Tighten up nailing on interior stair wall to 4" edge			
	5. Install missing nuts on hold downs			
6	6. Great room shearwall to extend up truss to roof per 4/S4			
7	7. Engineer fix needed for bottom plate being cut out at hold downs. SSTB bolts installed			
	too deep in foundation			
INSTRUCTIONS: Ok to cover exterior, corrections can be seen later				
NEXT INSPECTION: Plumbing/mech				
RE-INSPECTION FEE DUE? V NO YES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iessica.contratto @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 				