INSPECTION REPORT

| PERMIT NUMBER: | BP-15-00153 | OWNER'S NAME: | ARLI |
|--|------------------|---------------|-------------------|
| DATE: | 12/4/2015 | TYPE: | Exterior shear |
| TIME STARTED: | 2:08 PM | INSPECTOR: | Jessica Contratto |
| MAP NUMBER: | 18-19-29010-0005 | | |
| No shear nailing required on this structure | | | |
| 2. Treating as a final inspection | | | |
| 3. Framing ok | | | |
| 4. Trusses require continuos lateral bracing on bottom chord at 10'. General note 2 on | | | |
| truss sheets (circled) One on each side of truss is sufficient | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| INSTRUCTIONS: Complete truss bracing, call for re-final when complete | | | |
| | | | |
| NEXT INCRECTION | | | |
| NEXT INSPECTION: re-inspect | | | |
| RE-INSPECTION FEE DUE? VES \$ | | | |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: | | | |
| iessica.contratto @co.kittitas.wa.us | | | |
| • INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • | | | |