INSPECTION REPORT

PERMIT NUMBER:	BP-15-00299	OWNER'S NAME:	PERAVOZ
DATE:	3/11/2016	TYPE:	Framing
TIME STARTED:	1:19 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	21-14-34060-0003		
 NOTE: Framing inspection can not be performed prior to plumbing & mechanical inspection Engineer letter needed for CS staps @ windows Tighten up interior shear nailing @ stairs and fireplace Provide engineer requirements for stitch nailing @ hold downs Plumbing not complete Mechanical not installed 			
INSTRUCTIONS: Complete above corrections/Re-Inspection			
NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE I	NSPECTOR AT THE FO	
	ADDRESS:	iusiin benneff (a)	CO.KILLILAS.WA.US

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506