INSPECTION REPORT

IIIOI ECITORI NEI ONI			
PERMIT NUMBER:	BP-16-00224	OWNER'S NAME:	BOURNE
DATE:	12/7/2016	TYPE:	Exterior shear
TIME STARTED:	1:00 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-16-05030-0010		
 Tighten up SW3 nailing (1st Flr east and west of window wall) Complete CS14 straps (9) @ window wall - provide pictures Complete Flr to Flr CS14 straps @ east and west of window wall (8) locations - provide pictures 			
INSTRUCTIONS: C	omplete above/Provide pictures fo	or CS install	
NEXT INSPECTION: Plumb/Mech			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS:	<u>iustin.bennett</u> @	co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506