INSPECTION REPORT

PERMIT NUMBER:	BP-16-00644	OWNER'S NAME:	NELSON
DATE:	12/7/2016	TYPE:	Shearwalls
TIME STARTED:	1:27 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-16-05030-0006		
 Engineer to approve revised nailing schedule using 6d x 2" ring shank nails in lieu of 8d per shear schedule Does revised nailing schedule apply to all original shearwalls? Shearwall panels need to attach to sill plate. All panels currently not. Engineer needs to address Complete nailing at bottom of front dormer panels Hold downs ok 			
INSTRUCTIONS: Do not cover exterior. Engineer approval needed			
NEXT INSPECTION:	Re-inspect possibly		
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			
	MDDI/E33	<u> </u>	co.nicticas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506