
REPLAT OH TRACT PALOM ONI FIELDS PLAT DIVISION

PORTION OF S X OF HH Z KITTITAS OF SECTIO: COUNT 27, TOWNSHIP WASHINGTON NORTH, RANGE 8 EAST,



Existing thirty-foot Right-of-Way. (30.00')Z 0 - Kittitas 内 S County

Road

- The short plat name is show developed by Mr. Leroy J. "KITTITAS CO. SHORT PLAT NO. to this same short plat as "S filed under the Kittitas 418140. shown on top of the short plat J. Preston in November, 1977, to be NO. 77-12", but the County refers is "SHORT PLAT A-22". Said plat is as County Auditor's File Number as
- Not Used
- Not Used
- Not Not
- Used
- Found a 5/8-inch iron p from the calculated pos in N 17.22'22" E a (distance corner

0

N

- Found a 5/8-inch distance of 0.3' line. <u>+</u> p 0 5 without surveyor's calculated position (s cap of the property
- Land Corner Rec Kittitas County Number 536434. Auditor's Section Corner is filed with the the Auditor's File
- Land Corner Record for Section Corner Kittitas County Auditor's Office un Number 199912150012. under t filed with the Auditor's the File
- Land Corner Record for Kittitas County Auditor' Number 199912150013. Section Corner the filed with Auditor's file
- A thirty-foot (30.00' Easement dedicated via recorded. Palomino County Field Road Plat -Right-@f-Way Division II as
- County Road Right-of-Way drawing filed in Book 20 County Auditor's File No as detailed on 22 of Surveys, 199702200014 the Page Record of Survey 174, Kittitas

0 Ħ Ħ

- Historically two different location of the north quarter corner of Section 27 Township 18 North, Range 18 East. W.M. have been used. In 1977 via the short plat recorded under Kittitas Co. Auditor's File Number 418140, a monument was set. Subsequently the monument was removed possibly do to road reconstruction. In 1991 via the survey recorded under Kittitas Co. Auditor's File Number 539177, a nail and washer was set with a note that Kittitas Co. Public Works will set a monument in a monument case with future road maintenance in the vicinity. The location of these two monuments differ by 28.24 feet.
- The 3-inch brass cap monument found at the intersection of Reecer Creek Road and Bowers Road was held to establish the north boundary of the northwest quarter of said section 27. By holding this monument property on the north side of this line had the fewest apparent negative impacts, while the property immediately on the south side absorbed all the decrease in size. In addition, most performed subsequent to 1991 have relied on this monument as the location of the north quarter corner.
- However, the 1977 monument location was held for of locating the following three parcels: the purposes

W

Kittitas Co. 418140 Short Plat No. A-22 recorded under AFN

Tract 1 of Statutory Warranty Deed 201410160051 recorded under

Tract 2 of 201410160051 Statutory Warranty Deed recorded under AFN

p confirm the boundaries of said Short Plat.

were

used

to

The west quarter corner of Section 27 recorded on Said Auditor's File Number 418140 was calculated. However, on an adjacent survey to west, a 1-1/4 inch iron pipe was found and accepted as said west quarter corner. During this survey said 1-1/4 inch iron pipe was found and accepted as said west quarter corner.

The county road right of way for Reecer Creek Road has defined differently by various plats along Reecer Creek s peen Apad.

Ü

After contacting Kittitas County and doing independent records research we found no specific description of said right of way other than the previously recorded plats. Therefore with no other evidence, for this survey, the centerline of the county road known as Reecer Creek was defined in the northeast quarter of the northwest quarter of said Section 27 as coincident with the east boundary of the northwest quarter of said section. The said centerline matches that of said Auditor's File Number 418140.

The remaining exterior property boundary lines are identified on Sheet 1 of 5 as per the property description contained herein. However, the owner of said property owns addition adjoining property in this general

INSTRUMENT USED

INDEXING


DATA

Trimble R10 GPS Receivers

Traverse Closure Meets Standards Per WAC 332-130-090

R18E

0



0 \bigcirc

This is a intended to o show, nor does it purport to easements and encumbrances.


C19

RADIUS 200.00' {200.00'} 1000.00' {1000.00'} 545.52' {545.52'} 500.00'}

104.56' {104.56'} 73.22' {73.22'} {115.80'}

53.50' {53.50'} 36.63' {36.63'} {36.63'} 58.12' {58.12'} {59.59'}

CHORD BEARING
S 17'37'48" E
{S 17'37'48" E}
S 30'30'34" E
{S 30'30'34" E}
S 22'19'49" E
{S 22'19'49" E}
S 20'46'33" E}



		Nacadicko de distribujos como	West of the Second Second
1328 E. Hunter Place, Moses Lake, Washington	A TERRA DEVELOPMENT SERVICES CORPORATION	ENGINEERING & SURVEY	WESTERN PACIFIC

T:(509)765-1023
Services in Wast F:(509)765-1298

Surveyed by Drawn by Checked by by Tml/ INC Scale Sheet Project 4 N N/A 5 18146

181827