



Photos taken summer 2022 at Site 1 of old power and water lines leading to the cabin encouraging erosion straight to cabin. Proposal is to cut and remove these.








Photo of Site 2 taken in 2019. A tree has fallen but water still flows past it freely.



Photo of Site 2 taken in the Fall of 2021. Fallen trees due to erosion down stream created dam and increasing erosion at Site 1.



Notice where fire pit is in location to shore, 2019. Fire pit is in white circle.



Photo of Site a taken in the fall of 2021 before the massive erosion just a few months later.



Photo from Spring of 2022 showing proximity of cabin to Site 1 and Site 2.




Photo of Site 1 and Site 2 taken in the Spring of 2022. You can still see the waves crashing on Site 1 and water swirling at the dam of Site 2. Notice how much erosion at Site 1 has occurred since a few months before in 2021.