## **INSPECTION REPORT**

OWNER'S NAME: WEST

PERMIT NUMBER: BP-15-00215

DATE:		1/14/2016		TYPE:	Framing			
TIME S	TARTED:	11:14 AM		INSPECTOR:	Jessica Contratto			
MAP N	IUMBER:	20-14-24050-05	17					
	Stamped truss sheets not on site							
	2. A35 clips at gables per shearwall schedule and red pen on page A7							
	3. Strap top plate to header over slider at kitchen to porch							
	4. detail for outlookers shows inverted inverted LUS26 on interior end per 11/D5							
	5. Post down between floors in stairwell at multiple trimmer locations							
	6. Beam changes at rear patio ok							
	7. Skewed hangers for trusses above furnace? Provide attachment clarification from							
	manufacturer							
	8. Gas at 9#, not sufficient for test							
	9. CS16 x 48" straps over decorative beams. Bubbled page A5							
	10. Post down under header carrying beam at poder room door by office							
	11. Complete upper draftstop at fireplace. Solid filled cavity of insulation will provide							
	draftstop in stud bays at lower draftstop							
INSTRUCTIONS: Complete above, re-inspect								
NEXT INSPECTION: re-inspect								
RE-INSPECTION FEE DUE? VES \$								
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION								
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:								
iessica.contratto @co.kittitas.wa.us								
<ul> <li>INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694</li> </ul>								

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

## **INSPECTION REPORT**

PERMIT NUMBER:		BP-15-00215	OWNER'S NAME:	WEST					
DATE:		1/14/2016	TYPE:	Framing					
TIME STARTED:		11:14 AM	INSPECTOR:	Jessica Contratto					
MAP NUMBER:		20-14-24050-0517							
	Dogo 2								
	Page 2	TCV nanar habind firantage							
	12. Provide FSK paper behind fireplace								
	13. Address top plate breaks at decorative truss bottom chords along fireplace wall  14. Correct cut out shearwall in kitchen								
	15. Shearwall omitted in stairwell. Obtain revision								
INSTRUCTIONS: Complete above, re-inspect									
NEXT INSPECTION: re-inspect									
RE-INSPECTION FEE DUE? VES \$									
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION									
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:									
	iessica.contratto @co.kittitas.wa.us								
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>									