INSPECTION REPORT

OWNER'S NAME: COWGER

TYPE: Exterior shear

PERMIT NUMBER: BP-15-00284

DATE:

3/21/2016

TIME STARTED:		1:13 PM	INSPECTOR:	Amber Green
MAP NUMBER:		20-15-29050-0244		
	1. Tighten	up exterior nailing where mai	rked.	
	Interior shearwall and hold downs behind fireplace OK.			
	3. Will see remainder of interior shearwalls at framing inspection.			
			<u> </u>	
INSTRUCTIONS: Next inspector: framing revision to interior shearwalls kitchen area. See attached				
	С	hanges. OK to cover exterio	r after above complet	e.
NEXT I	NSPECTION:	Plumbing/Mechanical Prior t	to Framing	
RE-INSPECTION FEE DUE? VES \$				
	IF REC	QUIRED, RE-INSPECTION FEES MUS	ST BE PAID PRIOR TO SCH	IEDULING A RE-INSPECTION
	QI	JESTIONS? PLEASE CONTACT THE I		
amber.green @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				
	4.	11 N. Nuby Street, Suite 2, Literisble	AIB, WA JOJZO • IVIAIII O	THEC LINE. 303-302-7300