



KITITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

# INSPECTION REPORT

PERMIT NUMBER: BP-15-00688                      OWNER'S NAME: COLLINS  
 DATE: 11/9/2015                                      TYPE: Post holes  
 TIME STARTED: 11:52 AM                         INSPECTOR: Jessica Contratto  
 MAP NUMBER: 19-15-06000-0067

1. Setbacks ok
2. No Rebar grids in footings per plan. No rebar seen on site
3. Are 6x10 posts at edge of slab referred as "constrained"? Posts must have slab on all sides. If so, post holes must be 52" wide per plan. Post hole diameter currently meets "unconstrained" detail, but depth is per "constrained" detail. Depth must be 5.5' if unconstrained
4. 6x10 post holes toward rear of building ok

**INSTRUCTIONS:** Do not pour until reinforcement is inspected and clarification, approval or fix for "mixed type" footings at front main frame posts. Call with questions 509-962-7695 office, 509-899-1863

**NEXT INSPECTION:** re-inspect

RE-INSPECTION FEE DUE?     NO     YES    \$ \_\_\_\_\_  
**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

\_\_\_\_\_ [jessica.contratto@co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

• **INSPECTION REQUEST LINE:** [www.co.kittitas.wa.us/cds/request.asp](http://www.co.kittitas.wa.us/cds/request.asp) or 509-962-7694 •  
 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506