



This photo was taken from the left bank of Manastash Creek on the Schwab property. Two large cottonwood trees fell into the creek and are creating a flood hazard for surrounding properties in their current alignment.


The blue lines show the approximate Ordinary High Water Marks of Manastash Creek (~20'). The red dashed lines show the approximate cut locations for the two trees. The broken tops will remain on the right bank, but the trucks will be picked up from the center of the channel and relocated along the left bank less than 50 feet downstream from this location.







This photo is taken from the left bank, within the ordinary high water mark of Manastash Creek. The dashed red lines show the approximate locations where the trunks will be cut. The trunks within the main channel will be removed in full suspension and placed less than 50 feet downstream on the left bank.



This photo is a close up of the trunks to be relocated to the left bank downstream to reduce flood risks to surrounding properties.

Cottonwood Logs in Channel



Unvegetated bank where cottonwood trunks will be placed

