


SDS
 RECEIVED
 MAR 20 2022



- Approximate Extent of Landslide and Location of Cracking
- PSE Electrical Vault
- PSE Underground Power Service to Residence
- Waterline from Community Well to Residence
- Approximate Property Boundary
- Toe of Cut Slope for Building Pad Excavation

- Photo 1, @ Vault looking North to House
- Photo 2, East of Vault looking West Along Road
- Photo 3, North East of Vault looking up and along road showing head scarp of slide
- Photo 4, North of Vault showing top of Slide and vault settlement
- Photo 5, @ Toe of Slope looking up and east at cut slope failure
- Photo 6, @ Toe of Slope looking east along toe
- Photo 5, @ Toe of Slope near mid point of cut showing local cut failure and small slide zone causing heave of existing grade near house

Approximate location of previous slope mitigation work. Mitigation involved drains and grading to drain water from slope. Water drains into roadside swale on South side of Cul-de-Sac.

Casto Residence 561 Palouse Dr. Cle Elum, WA Kittitas County Parcel # 953974
4/6/2021
Pg. 1/1
Slope Failure