



FIRE LIFE SAFETY INSPECTION REPORT

Building/Business Owner Name: A.C.X Inspection Date: 1/20/2016
 Business Name: ACX Pacific Address: 5693 Vantage Hwy
 Inspection Issued To: Eric Hull Mailing Address: SAME
 Type of Business: Hay Processing Business phone number: 509-962-7800

A fire inspection has been conducted on your property. During this inspection conditions affecting fire/life safety may have been noted.

A. Exterior Assessment	E. Fire Alarm System	I. Kitchen Suppression	
1 - Building number not posted	1 - Alarm Service Report	1 - Cleaning of hood and duct	
2 - Obstructed FDC	2 - Devices obstructed	2 - Illegal cooking operation	
3 - Obstructed fire hydrant	3 - Alarm Maintenance	3 - Six month service needed	
4 - Gas meter protection	F. Flammable/Combustible Liquids	J. Automatic Sprinkler	
5 - Storage proximity	1 - Storage cabinet	1 - Annual service needed	X
6 - Storage under eaves	2 - Improper housekeeping	2 - FDC cap needed	
B. Exits	3 - No storage area	3 - Hanging material	
1 - Exit travel	4 - Close to heating appliance	4 - Sprinkler clearance	
2 - Exits obstructed	5 - Fueled equipment	5 - Provide sprinkler protection	
3 - Panic hardware	6 - Oily rags	6 - Damaged/Painted heads	
4 - Number of exits	7 - Compressed gas tanks	7 - Spare heads and/or wrench	
5 - Unapproved locking devices	8 - Equipment rooms	K. Fuel Dispensing	
C. Exit Lighting and Signs	G. Electrical	1 - Fire extinguisher	
1 - Exit signs battery backup	1 - Extension cord usage	2 - Emergency shutoff	
2 - Exit signs required	2 - Electrical panel labeling	3 - Provide signage	
3 - Emergency lighting	3 - Portable heaters	4 - Replace hoses	
4 - Exit sign burnt out	4 - Improper power strip usage	L. Hotel/Apartments	
5 - "to remain unlocked" sign	5 - Panel obstructed	1 - Evacuation routes	
D. Extinguishers	6 - No cover plate	2 - Fire alarm system	
1 - Class K extinguisher	7 - Multi-plug adapter	3 - Smoke detectors	
2 - Number of extinguishers			
3 - Extinguisher placement	H. Fire Walls and Doors	X. No Apparent Violations	
4 - Extinguisher obstructed	1 - Restrained fire door	1 - No Apparent Violations	
5 - Extinguisher maintenance	2 - Breached wall or ceiling		
6 - Signs indicating location	3 - Fire assembly needs repair		

Notes: Please get the Fire Suppression system inspected.

Remarks:

\$640.00

This Fire Inspection reports also serves as your invoice. Please remit payment in the amount of \$ 640.00 within 30 days.

Inspector: Josh Hawk - DFM Received By: Eric Hull

SIGNATURE Eric Hull PRINT NAME Eric Hull DATE 1/20/16