



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-13-00659

OWNER'S NAME: CRAIG REIMER CONST.

DATE: 5/11/2015

TYPE: Framing

TIME STARTED: 10:40 AM

INSPECTOR: Jeremy Haberman

MAP NUMBER: 20-15-19051-0080

	1. H10 Clips Required at All 2x10 Rafters Over Entry. See Section A-A on A1.
	2. Strap Top Plate to Header Above Entry Door
	3. Additional Truss Bracing Required at B Trusses.
	4. Engineer Stamped Truss Sheets Need to Be Verified at Insulation.
	5. Interior Shear OK.
	6. Add Stub in Master Bedroom Wall Under Doubled PSL.
	7. Strap Double Break in Top Plate in MAster Bedroom, Over Garage Man Door

INSTRUCTIONS: Make Corrections Above. OK to Insulate.

NEXT INSPECTION: Insulation.

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ jeremy.haberman@co.kittitas.wa.us

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506