



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

## INSPECTION REPORT

PERMIT NUMBER: BP-14-00166 OWNER'S NAME: THE PASS LLC  
DATE: 10/7/2014 TYPE: Exterior shear  
TIME STARTED: 12:59 PM INSPECTOR: Amber Green  
MAP NUMBER: 22-11-04055-0026

	1. P2-2 shearwall missing horizontal nailing at panel edge.
	2. (2) rows nailing per shearwall schedule at panel edges at front shearwalls.
	3. There are straps still missing per 11/S900 at windows.
	4. 3x sill plate missing at P2 shearwalls - obtain engineers fix/approval.

INSTRUCTIONS: Complete Above, then OK TO COVER.

NEXT INSPECTION: FRAME/PLUMB/MECH

RE-INSPECTION FEE DUE? ☒ NO ☐ YES \$ \_\_\_\_\_

**IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION**

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

\_\_\_\_\_ amber.green @co.kittitas.wa.us

• INSPECTION REQUEST LINE: [www.co.kittitas.wa.us/cds/request.asp](http://www.co.kittitas.wa.us/cds/request.asp) or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506