INSPECTION REPORT

BP-14-00434

PERMIT NUMBER:

OWNER'S NAME: BURNSTEAD

DATE:		11/13/2014	TYPE:	Exterior shear
TIME STARTED:		12:27 PM	INSPECTOR:	Amber Green
MAP NUMBER:		20-14-13050-002	4	
	Hold down at P4 missplaced at office wall.			
	2. Hold downs missing at P4 at garage west wall. Nail per plans.			
	3. Re-check nailing at P2 walls at upper floor. To be 2" o.c.			
INSTRUCTIONS: Obtain engineers approval/change for #1 and #2. Complete #3. Call for re-inspection.				
NEXT	INSPECTION	l: Re-Shear		
RE-IN	SPECTION F	EE DUE? NO	YES	\$
	IF R	EQUIRED, RE-INSPECTION FEES MU	ST BE PAID PRIOR TO S	CHEDULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
	amber.green @co.kittitas.wa.us			
		ECTION REQUEST LINE: <u>www.co</u> 411 N. Ruby Street, Suite 2, Ellensbu		