INSPECTION REPORT

| INSI ECHON KEI OKI | | | |
|--|------------------|---------------|-------------------|
| PERMIT NUMBER: | BP-15-00251 | OWNER'S NAME: | MONTGOMERY |
| DATE: | 1/27/2017 | TYPE: | Final |
| TIME STARTED: | 10:26 AM | INSPECTOR: | Jessica Contratto |
| MAP NUMBER: | 20-16-33050-0003 | | |
| Framing ok Truss bracing missing per truss sheets Trusses require rigid ceiling applied to bottom chord. Obtain revised sheets clarifying if additional bracing will be required with no ceiling | | | |
| INSTRUCTIONS: Complete above | | | |
| NEXT INSPECTION: re-inspect | | | |
| RE-INSPECTION FEE DUE? VES \$ | | | |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us | | | |
| | | | |

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506