INSPECTION REPORT

INSPECTION REPORT			
PERMIT NUMBER:	BP-16-00079	OWNER'S NAME:	DUNCKLEY
DATE:	8/17/2016	TYPE:	Shearwalls
TIME STARTED:	12:30 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	21-14-34053-0104		
1. Nailing not per shear schedule on "D" shearwalls (clouded on dwgs) 2. Nailing not per shear schedule on "C" shearwalls (clouded on dwgs) 3. Install A35's @ Interior shearwall "B" in garage per 7/S2.0 4. Obtain engineer approval for added window in Masterbath in shearwall "A" (2) locations 5. DO NOT COVER INSTRUCTIONS: Tighten up nailing/Provide engineer approval for added windows/Re-Inspection			
NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:_

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iustin.bennett @co.kittitas.wa.us