INSPECTION REPORT

IIIOI ECITOR REI ORI			
PERMIT NUMBER:	BP-16-00407	OWNER'S NAME:	WHORLEY
DATE:	4/13/2017	TYPE:	Framing
TIME STARTED:	12:02 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-15-19050-0123		
1. Outlookers not per F/S4 - Provide engineer letter 2. Deck ledger not per D/S1 - SDS not installed 3. Provide engineer approval for deck roof changing to Rafter vs. Truss 4. Install Draftstop @ roof line Upstairs INSTRUCTIONS: Complete above/Verify @ insulation			
NEXT INSPECTION:			
Insulation			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:_

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iustin.bennett @co.kittitas.wa.us