INSPECTION REPORT			
PERMIT NUMBER:	BP-16-00487	OWNER'S NAME:	CARNEY
DATE:	10/21/2016	TYPE:	Framing
TIME STARTED:	9:53 AM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	19-20-32000-0008		
<ol> <li>Photos Saved to 'T' Drive.</li> <li>Not Ready for Framing Inspection. Plumbing, Mechanical and Electrical to Be C ompleted Prior to Framing.</li> <li>Shear Inspection Not Completed Prior to Cover. Shear NAiling Verification Required. OK per MF 10/27/16</li> </ol>			
INSTRUCTIONS: Contact Building Official Regarding Missed Shear NAiling Inspection.  NEXT INSPECTION: Polyspect			
Nemspect			
RE-INSPECTION FEE			\$ 86.00
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE I		
	ADDRESS: jei	<u>remv.haberman</u> @	co.kittitas.wa.us

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506