INSPECTION REPORT

PERMIT NUMBER:	BP-16-00487	OWNER'S NAME:	CARNEY
DATE:	5/4/2017	TYPE:	Re-inspection
TIME STARTED:	3:35 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-20-32000-0008		
 Gas @ 0# - Needs to be 15# C6 Glulam header @ utility rm entry - red crayon on header C8 Provide 3-1/8x11-1/4 GLB @ E Roof - Engineer letter not on file or on site C10 Provide 5-1/8x11-1/4 GLB above dining - Engineer letter not on file or on site C13 Provide adequate bearing - South of kitchen indicated in red crayon C15 Provide installation manual for fire place - owners manual on site does n ot have clearances C16 Provide clips or equivalent @ porch truss midpt - clouded on truss sheets (nails not acceptable) Provide truss manufacturer approval for modifying truss top cord @ outlookers REFEE 			
INSTRUCTIONS: REFEE/Complete above/Provide Engineer Letter NEXT INSPECTION: Re-Inspection RE-INSPECTION FEE DUE? NO YES \$ 86.00			
	DUE? NO VES	PAID PRIOR TO SCHE	\$ 86.00 DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS:iustin.bennett @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506