INSPECTION REPORT

PERMIT NUMBER:	BP-16-00651	OWNER'S NAME:	TALISMAN
DATE:	3/22/2017	TYPE:	Insulation
TIME STARTED:	11:45 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-15-19056-0006		
 Corretion 1 - Truss ok for sprinkler in top chord - not complete C2 - 8x8 post @ loft beam - not complete C5 - Strap @ master top plate/steel beam - not complete C6 - Engineer fix for porch posts - not complete Other corrections Ok Upstairs Bathroom Exhaust Fans disconnected Wall insulation - Batt w/ vapor barrier - Ok Rafter Insulation - Batt w/ vapor barrier - Ok DO NOT COVER INSTRUCTIONS: DO NOT COVER/Complete above corrections			
NEXT INSPECTION: Re-Inspection			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:_

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iustin.bennett @co.kittitas.wa.us