



THIS ELEVATION IS NOT ADEQUATE  
 (NO KNOWN LANDMARKS, NON-ADEQUATE  
 DETERMINATION OF SLOPE SINCE  
 SLOPES ARE NOT STRAIGHT LINES, AND  
 BECAUSE THE PROPOSED STRUCTURE ELEVATION IS NOT TO SCALE)

HOWEVER, IT IS APPARENT THE STRUCTURE  
 IS MORE THAN THE REQUIRED 115' FROM  
 OHWM.

RSB 4:22:16

