## **INSPECTION REPORT**

PERMIT NUMBER:		BP-14-00079	OWNER'S NAME:	MILLER	
DATE:		9/3/2014	TYPE:	Re-inspection	
TIME STARTED:		12:49 PM	INSPECTOR:	Amber Green	
MAP NUMBER:		20-15-20058-0015			
	1. Re-check	truss bracing per truss sheets	. Bracing missing	in master bedroom and great r	
	oom gable ends.				
	2. Truss clips at every truss at shearwall locations per plans.				
	3. The P1-6 needs to extend into the trash area per plans.				
	4. Over framed areas need to be supported per 7/D3.				
	5. Do you have approval from the engineer for the ledger supporting the attic trusses in t				
	he garage?				
	6. Area above garage not on plans. No access allowed without revisions.				
	7. Complete shear transfer at P1-6 to truss per plans in garage.				
	8. D1 and D2 truss sheets different than trusses installed. Obtain new sheets.				
	9. CS straps missing at kitchen window.				
INSTRUCTIONS: Re-Fee, Re-Call. Complete above.					
NEXT INSPECTION: Re-Inspection					
RE-INSPECTION FEE DUE? VES \$ 65.00					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	amber.green @co.kittitas.wa.us				
■ INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ■  411 N. Ruby Street, Suite 2. Ellensburg, WA 98926 ■ Main Office Line: 509-962-7506					