INSPECTION REPORT

PERMIT NUMBER:	BP-14-00092	OWNER'S NAME:	RADICH
DATE:	11/21/2016	TYPE:	Final
TIME STARTED:	1:57 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-19-29054-0003		
 All posts and beams in garage must be drywall wrapped and taped. All penetrations in ceiling and walls must be sealed Doors from garage must be self closing Provide solid or fire-rated self-closing door at under-stair area. Otherwise area must become part of garage fire separation. Kitchen added in upstairs. Not on plan. Additional permit fees required for added fixtures Room upstairs will be used for sleeping purposes. Smoke detector currently in stalled. Smoke/CO needed outside bedroom Submit revised floor plan showing kitchen and other habitable room Blower door test not performed. Will determine if necessary Handrails at stairs must return to the wall at ends 			
INSTRUCTIONS: Complete above,do not occupy NEXT INSPECTION: Re-inspect			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:_

iessica.contratto @co.kittitas.wa.us

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506