INSPECTION REPORT

| PERM | T NUMBER: | BP-15-00207 | OWNER'S NAME: | IVERSON |
|---|--|------------------|---------------|-----------------|
| DATE: | | 12/31/2015 | TYPE: | Final |
| TIME STARTED: | | 10:21 AM | INSPECTOR: | Jeremy Haberman |
| MAP NUMBER: | | 20-14-19053-0002 | | |
| | 1. Permit Card Not Onsite. Septic OK Access OK. | | | |
| | 2. Garage Truss Fix Not Able to be Verified. Provide Taller Ladder at ReInspect. | | | |
| | 3. Fire Marshall Final Not Completed. Fire Marshall WUIC Final Required Prior to Building | | | |
| | Final. | | | |
| | 4. Blower Door Test Results Not Onsite. Insulation Certificate OK. | | | |
| | 5. Not Able to Verify Energy Credits. Provide Documentation of Heat Pump Water Heater Effe | | | |
| | ciency of 2.0 | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| INSTRUCTIONS: Complete Fire Marshal Final and MAke Corrections Above. Call for ReInspection. | | | | |
| | | | | |
| NEXT INSPECTION: Final | | | | |
| RE-INSPECTION FEE DUE? VES \$ | | | | |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS: | | | | |
| | ieremv.haberman @co.kittitas.wa.us | | | |
| INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 | | | | |